

Fig. 1

C

Cr, Mo, N





Fig. 2

2/4

Hardness, HRC



Tempering temperature, °C

Fig. 3




Fig. 4

3/4




Fig. 5




Fig. 6

4/4




Fig. 7